

REPLACEMENT FOR

SONATA 92~



FRONT BUMPER
901.HY04993BA
OE:86560-38000




HEAD LAMP
930.HY1105
R 92102-33550 L 92101-33550




REAR BUMPER
901.HY04994BA
OE:86610-33550



CORNER LAMP
938.HY1501
R 92302-33550 L 92301-33550




TAIL LAMP
933.HY9001
R 92406-33500 L 92405-33500



TAIL LAMP
931.HY9535
R 92402-33500 L 9201-33500



GRILLE
900.HY07618GA
OE:86350-33550



DOOR MIRROR
980.HY901E
R 87606-33550 L 87605-33550



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com