

REPLACEMENT FOR

SONATA '09~



FOG LAMP
939.HY2027 321-2027
R 92202-3K500 L 92201-3K500




BUMPER GRILLE
901G.HY04096BA
OE:86561-3K500




HEAD LAMP ELECTRIC
930.HY1148E 221-1148-EM
R 92102-3K520 L 92101-3K520



GRILLE
900.HY07911GA
OE:86351-3K800



FRT BUMPER MOULDING UP
923.HY55840A
OE:86585-3K500



HEAD LAMP
930.HY7010
OE:



FRONT BUMPER
901.HY07008GB
OE:86511-3K700



BUMPER MOULDING SIDE
923.HY55841A
OE:R 86582-3K700 L 86581-3K700




TAIL LAMP
931.HY1929
R 82402-3K010 L 83401-3K010



REAR BUMPER
901.HY07009GB
OE:8661-3K800



BUMPER MOULDING SIDE CHROME
923.HY55842A
OE:



BACK LAMP
933.HY1303
R 92404-3K020 L 92403-3K020



FRONT BUMPER REINFORCEMENT
911.HY44019A
OE:



RADIATOR SUPPORT
904.HY30347A
OE:64101-0A500



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com