

REPLACEMENT FOR
SONATA '17



FOG LAMP
939.HY7252
R:92208-C1500 L:92207-C1500



TAIL LAMP LED
933.HY7319
R:92404-E6600 L:92403-E6600



FRONT BUMPER
901.HY07059BA
OE:



HEAD LAMP ELECTRIC
930.HY7063E
R:92102-C1500 L:92101-C1500



DRL
939.HY7253
R:92208-C1700 L:92207-C1700



TAIL LAMP
931.HY7116
R:92402-C1500 L:92401-C1500



REAR BUMPER
901.HY07060BA
OE:86610-C1710



HEAD LAMP
930.HY7064
R:



REAR FOG LAMP
932.HY7031
R:92406-C1500 L:92405-C1500



TAIL LAMP LED
931.HY7117
R:92402-C1600 L:92401-C1600



REAR BUMPER MID
901.HY07061BA
OE:86612-C1740



HEAD LAMP
930.HY7065
R:92102-C1620 L:92101-C1620



BACK LAMP
933.HY7317
R:92404-C1500 L:92403-C1500



TAIL LAMP LED
931.HY7118
R:92402-E6600 L:92401-E6600



REAR BUMPER LOWER
901.HY07062BA
OE:86612-C1700



HEAD LAMP
930.HY7066
R:



BACK LAMP LED
933.HY7318
R:92404-C1600 L:92403-C1600



GRILLE
900.HY08016GA
OE:86350-E6AA0



REAR BUMPER LOWER
901.HY07063BA
OE:86612-C1730

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com

REPLACEMENT FOR

SONATA '17



REAR BUMPER SIDE BRACKET
911.HY44380A
R:86556-C1700 L:86555-C1700




RADIATOR SUPPORT
904.HY30937A
OE:64101-C1700



FRONT BUMPER BRACKET
911.HY44630A
R:



BUMPER GRILLE
901G.HY04130BA
OE:86561-E6700



REAR BUMPER BRACKET
911.HY44376A
R:86614-C1700 L:86613-C1700



DRL COVER
913.HY07043
R:86522-C1AB0 L:86521-C1AB0



COVER, HOOD UNDER
911.HY44631A
OE:86361-C1700




FRONT BUMPER REINFORCEMENT
911.HY44377A
OE:86530-C1700



FRONT INNER FENDER
915.HY11137
R:86812-C1500 L:86811-C1500



FRONT BUMPER REINFORCEMENT
911.HY44383A
OE:64900-C1720



TRAILER COVER
901C.HY0004
OE:86517-E6700



REAR BUMPER REINFORCEMENT
911.HY44378A
OE:86631-C1700



REAR INNER FENDER
915.HY11138
R:86822-C1500 L:86821-C1500



FRONT BUMPER STRIPE CHROME
923.HY55876A
R:86552-C2AA0 L:86551-C2AA0



HOOD
902.HY20959A
OE:66400-C1500



FRONT BUMPER SUPPORT UPPER
911.HY44379A
OE:86570-C1700



COVER, ENGINE UNDER
957.HY22025A
OE:29110-C1600



FRONT BUMPER STRIPE SPORT TYPE
923.HY55877A
R:86564-C2800 L:86563-C2800



FRONT FENDER
905.HY20965A
R:66311-C1500 L:66321-C1500

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.




HY

email:market@daiwa-motor.com

REPLACEMENT FOR
SONATA '17







FRONT DOOR
907.HY28143A
R:76004-C1500 L:76003-C1500



REAR DOOR
907.HY28144A
R:77004-C1500 L:77003-C1500



TRUNK LID
928.HY21033A
OE:69200-C1500



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.