

REPLACEMENT FOR

iX 35 '10~



FOG LAMP
939.HY7203
R 92202-2S000 L 92201-2S000



GRILLE
900.HY07619GA
OE:86351-2S100



FRONT BUMPER REINFORCEMENT
911.HY44009A
OE:86530-2S000



HEAD LAMP
930.HY7007
R:



REAR BUMPER LAMP
932.HY7008
R:92406-2Z300 L:92405-2Z300



FRONT BUMPER
901.HY07010BA
OE:86511-2S000



REAR BUMPER REINFORCEMENT
911.HY44014A
OE:86630-2S000



HEAD LAMP
930.HY7003
R:92102-2S000 L:92101-2S000



TAIL LAMP
933.HY7001
R 92406-2S000 L 9205-2S000



REAR BUMPER UPPER
901.HY07019BA
OE:86611-2Z000



FRONT BUMPER ABSORBER
911.HY44015A
OE:



HEAD LAMP CHINA TYPE
930.HY7003N
R 92102-2Z000 L 92101-2Z000



TAIL LAMP
931.HY7003
R 92402-2S000 L 92401-2S000



REAR BUMPER LOWER
901.HY07020BA
OE:



REAR BUMPER ABSORBER
911.HY44016A
OE:



FOG LAMP
939.HY7206
R:92202-2Z000 L:92201-2Z000



MIRROR
980.HY114E
OE:



GRILLE UNDER
900.HY07921GA
OE:86550-2Z000



BUMPER GRILLE
901G.HY04982BA
OE:86561-2S100

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com

REPLACEMENT FOR

iX 35 '10~



CROSSMEMBER
906.HY21006A
OE:62400-2S000



FRONT BUMPER BRACKET
911.HY44013A
R:86514-2S000 L:86513-2S000



RADIATOR SUPPORT
904.HY30938A
OE:64101-2X000




RADIATOR SUPPORT USA TYPE
904.HY30933A
OE:64101-3S000



COVER ENGINE UNDER
957.HY22008A
OE:29110-2S000



REAR BUMPER BRACKET
911.HY44034A
R:86614-2Z000 L:86613-2Z000



FRONT BUMPER MOULDING
923.HY55126A
OE:86352-2S100



FOG LAMP CASE
913.HY07010
OE:



AIR FILTER HOUSING
241.HY1018A
OE:82210-2Z000




FRONT APRON
903.HY50715A
OE:



FOG LAMP CASE
913.HY07009
OE:



WATER POT
509.HY5020A
OE



INNER FENDER
915.HY11100
R:86812-2Z000 L:86811-2Z000



MUDGUARD
922.HY9912Z
OE:



RADIATOR SUPPORT EU TYPE
904.HY30935A
OE:64101-2Y000



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com