

REPLACEMENT FOR

RIO '01~



TAIL LAMP
931.KA1913
R OK30A51040C L OK30A51030C



FRONT BUMPER
901.KA04979BA
OE:86510-FD040PAC



REAR BUMPER REINFORCEMENT
911.KA44768A
OE:86630-FD000



HEAD LAMP
930.KA1114
R 92102-FD001 L 92101-FD001



HEAD LAMP
931.KAA287
R OK3AL51150 L OK0AL51160



REAR BUMPER
901.KA05027BA
OE:



HEAD LAMP
930.KA1114C
R 92102-FD001 L 92101-FD001



FOG LAMP
939.KA2003
R 92202-FD000 L 92201-FD000



INNER FENDER
915.KA11148
OE:



HEAD LAMP
930.KA6535
R OK30A51040C L OK30A51030C




FOG LAMP COVER
913.KA2003
L 86525-FD000 R 86526-FD000



RADIATOR SUPPORT
904.KA30017A
OE:64100-FD000



HEAD LAMP
930.KAA611
R OK30A51040C L OK30A51030C



MIRROR
980.KA136
R 87620-1E030 R 87610-1E030



FRONT BUMPER REINFORCEMENT
911.KA44767A
OE:86530-FD000



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

KA

email:market@daiwa-motor.com