

REPLACEMENT FOR

COOPER R60



REAR BUMPER BRACKET
911.4944003
R:5112 9802 116 L:5112 9802 115



FENDER TRIM REAR
943.491105
R:5177 9800 770 L:8177 9800 769




GRILLE
900.4907002GA
OE:51 11 9 807 196



FRONT INNER FENDER
915.4901002A
R:5171 9807 830 L:5171 9807 829



BUMPER GRILLE MOULDING
923.4901007A
OE:51 11 9 804 005



FRONT BUMPER
901.4904003BA
OE:51 11 9 807 196



FRONT BUMPER CORNER
912.4901001
5111 9802 644 L:5111 9802 643





HEAD LAMP MOULDING
923.4901008A
R:5113 9801 574 L:5113 9801 573



FRONT BUMPER LOWER
901.4904004BA
OE:51 11 9 801 917



FENDER TRIM FRONT
943.491103
R:5177 9800 762 L:5177 9800 761



FRONT BUMPER GRILLE
901G.4902002BA
OE:51 11 9 804 004



FENDER TRIM F. FRONT
943.491104
R:5177 9801 886 L:5177 9801 885



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

MI

email:market@daiwa-motor.com