

REPLACEMENT FOR
B14 '94~



REPLACEMENT FOR
B15 '00~



REPLACEMENT FOR
RESORT



REPLACEMENT FOR
**SENTRA
'88**



HEAD LAMP
930.NS3022 215-1157
R 26010-2M125 L 26060-2M125



HEAD LAMP
930.NS7668
R 26025-4M420 L 26075-4M420



HEAD LAMP
930.NS1153 215-1153
R 26010-80R00 L:26060-80R00



HEAD LAMP
930.N51572
R B6010-84AA00 L B6060-B4A00



CORNER LAMP
938.NS3079 215-1566
R 26120-1M125 L 26125-1M125



CORNER LAMP
938.NS7003
R 26124-4M400 L 26129-4M400



CORNER LAMP
938.NS1561 215-1561
R 26130-75R00 L:26135-75R00




CORNER LAMP
938.NS3398
R B6120-75AA00 L B6125-75A00



INNER FENDER
915.NS11093
OE:



GRILLE
900.NS07992GA
OE:62310-4M460



TAIL LAMP
931.NS1771
R B65550-75A10 L B6555-75A10



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

NS

email:market@daiwa-motor.com