


REPLACEMENT FOR

POLARSUN LINGWE



REAR PANEL
926.TY32076A
OE:



FRONT BUMPER BRACKET(NEW)
911.TY44247
OE:



HEAD LAMP
930.PS1001
OE:



GRILLE PLATING
900.PS07001GA
OE:



FRONT BUMPER BRACKET(OLD)
911.TY44246
OE:



FOG LAMP
939.PS4001
OE:



GRILLE BLACK
900.PS07001GB
OE:



SIDE LAMP
932.PS1001X
OE:



HOOD
902.PS20001A
OE:



TAIL LAMP
931.TY1907
OE:



FRONTBUMPER
901.PS04001BA
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

PS