

REPLACEMENT FOR

ALTO

REPLACEMENT FOR

APV /CARRY '07~



HEAD LAMP ('06)
930.SZ7378
OE:



SIDE LAMP
932.SZ7001X
OE:



FRONT DOOR
907.SZ28003A
R:



TAIL LAMP ('06)
931.SZ7008
OE:



HEAD LAMP
930.SZ1133
R 35120-61J10 L 35320-61J10



GRILLE
900.SZ07702GA
OE:



REAR DOOR
907.SZ28004A
R:



FRONT BUMPER ('06)
901.SZ14002BA
OE:



TAIL LAMP
931.SZ9942
R 35650-61J00 L 35670-61J00



FRONT BUMPER
901.SZ04705BA
OE:



TRUNK LID
928.SZ11001A
OE:




HEAD LAMP ('12)
930.SZ7386
R:



MIRROR ELECTRIC
980.SZ018E
OE:



SIDE BUMPER
912.SZ04001
OE:



TAIL LAMP ('12)
931.SZ7016
R:



MIRROR
980.SZ018
OE:



SIDE BUMPER
912.SZ04002
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

SU

email:market@daiwa-motor.com