


REPLACEMENT FOR
SWIFT
'90~



REPLACEMENT FOR
SWIFT
'96~



REAR LAMP
931.SZ1912
R 35603-70C20 L 35604-70C20



BODY MOULDING
923.SZ9099
OE:



HEAD LAMP
930.SZ5601
R 35120-60B10 L 35121-60B30



HEAD LAMP
930.SZ1117
R 086639 L 086638



F.BUMPER (LOWER)
901.SZ04037BA
R.BUMPER (LOWER)
901.SZ04055BA



WIND BAR
946.SZ9099
OE:



CORNER LAMP
938.SZ1136
R 36115-60B020 L 36135-60B020




CORNER LAMP
938.SZ1516C
R:



F.BUMPER (UPPER)
901.SZ04036BA
R.BUMPER (UPPER)
901.SZ04054BA



AIR FILTER
806.SZ9099
OE:



CORNER LAMP
938.SZ1516A
R 086643 L 086642



GRILLE
900.SZ07099GA
OE:



TIMING BELT ENGINE COVER
947.SZ9099
OE:



FOG LAMP
939.SZ2210
OE:



GRILLE
900.SZ07098GA
OE:



REAR PANEL
941.SZ2902
OE:36255-70C00

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

SU

email:market@daiwa-motor.com