

REPLACEMENT FOR

COASTER BB20



GRILLE
900.TY07114GB
OE:53111-39035

REPLACEMENT FOR


COASTER BB42




LIGHT CASE
913.TY07147HA
R 53131-36010 L 53132-36010



HEAD LAMP
930.TY1276
OE:



CORNER LAMP
938.TY3089W
R 81550-39705 L 81560-39605




CORNER LAMP
938.TY1302
R 81510-39465 L 81520-39465




CORNER LAMP
938.TY3089A
R 81510-36280 L 81520-36220



TAIL LAMP
931.TY1478U
R 81550-39075 L 81560-39605



TAIL LAMP
931.TY3011U
R 81510-36280 L 81520-36220



LIGHT CASE
913.TY07114HB
R 53131-39115 L 53132-39115



GRILLE
900.TY07147GA
OE:53111-36010



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com