

REPLACEMENT FOR


COROLLA '76~on



LICENSE LAMP
212-2104
OE:81270-19245

REPLACEMENT FOR


COROLLA '80~on



FRONT LAMP - PU BUMPER
932.TY1259 212-1648
R 81510-19785 L 81520-19785




SIGNAL LAMP
932.TY1088 212-1502
OE:81730-19125



HEAD LAMP
930.TY7006 212-1118
R 81110-89159 L 81150-89159



TAIL LAMP
931.TY1456 212-1940
R 81550-80121 L 81560-80125



FRONT LAMP
932.TY1132 212-1607
R 81510-12220 L 81520-12210





CORNER LAMP
938.TY1027 212-1536
R 81610-19255 L 81620-19255



TAIL LAMP
931.TY1188 212-1912
R 81505-19415 L 81506-19285



TAIL LAMP
931.TY1049 212-1947
OE:R 81550-12390 L 12390



SIGNAL LAMP
932.TY1082 212-1503
OE:81730-19316



FRONT SIDE BUMPER
912.TY41007A 212-2815
R 52102-19175 L 52103-19155



TAIL LAMP
931.TY1911 212-1911
OE:R 81505-19205 L 81506-80017



FRONT LAMP
932.TY1157 212-1505
R 81510-12350 L 81520-12330



FRONT SIDE BUMPER
912.TY41008A 212-2816
R 52106-19135 L 52107-19165

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com