

REPLACEMENT FOR

HIACE YH133

'99



TAIL LAMP
931.TY1907 112-1907
OE:



FOG LAMP
939.TY2025
OE:



HEAD LAMP
930.TY1198 212-1198
R 81130-26230 L 81170-26130



MIRROR
980.TY254E
OE:



CORNER LAMP
938.TY15D7 212-15D7
R 81610-26070 L 81620-26070





'00 FRONT BUMPER
OE:



CORNER LAMP
938.TY15F8 212-15F8-A
R 81610-26080 L 81620-26080



FRONT BUMPER
901.TY04150BA
OE:



TAIL LAMP
931.TY19C4 212-19C4
R 81550-26330 L 81560-26330



FRONT GRILLE
900.TY07099GA
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com