


REPLACEMENT FOR

KIJANG 92~




FRONT LAMP
932.TY5105 212-1655
R:81510-38030 L:81520-38030



HEAD LAMP
930.TY1710 212-1145
R:81110-38020 L:81150-38020




TAIL LAMP BLACK
931.TY1347K 212-1914-2
R:81550-39785 L:81560-39785



CORNER LAMP BLACK
938.TY1885K 212-1566-6
OE:



FRONT SIDE BUMPER
912.TY04125PA 212-2820
OE:




CORNER LAMP
938.TY1885C 212-1566-1
R:81610-38010 L:81620-38010



FRONT SIDE BUMPER
912.TY04126PA 212-2821
OR:52152-90100 L:52153-90100



CORNER LAMP CLEAR CHROME
938.TY1886C
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com