

REPLACEMENT FOR

L/CRUISER FJ100 '98~



FOG LAMP
939.TYA119
OE:



TAIL LAMP CRYSTAL
931.TY3381 212-19B0
R 81550-60490 L 81560-60410



HEAD LAMP ELECT W/MOTOR
930.TYC387E 212-11P8
R 81130-60E40 L:81170-60E00



HEAD LAMP
930.TY1188 212-1188
R:81010-60020 L:81050-60020



TAIL LAMP
931.TY9157 212-1986
R:81550-60560 L:81550-60480



BACK LAMP
933.TY1316 212-1316
R:81580-60110 L:81590-60040



TAIL LAMP
931.TYB721 212-19T7
R:81551-60890 L:81561-60830



HEAD LAMP
930.TY11C1 212-11C1
R:81019-60040 L:81059-60040



TAIL LAMP
931.TY9157C 212-19E6-A-CR
OE:



GRILLE
900.TY07987GA
OE:



REAR BUMPER LAMP
932.TY2930
R:81580-60240 L:81590-60270



CORNER LAMP
938.TY6654 212-15C8
R 81510-60480 L 81520-60350



SIDE LAMP
937P.TY5727X 212-1410P-X1
OE:212-141P-X1



FRONT BUMPER
901.TY40901BA
OE:



FRONT BUMPER
901.TY05194BA
OE



CORNER LAMP
938.TY5543 212-15D3
R 81510-60490 L 81520-60360



SIDE LAMP
932.TY5727A 212-1410N-U
OE:81730-20191



BUMPER GRILLE
901G.TY05039BA
OE:

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com