

REPLACEMENT FOR

# L/CRUISER PRADO '18~



**FRONT BUMPER**  
901.TY05225BA  
OE:



**RADIATOR UPPER COVER**  
911.TY44376A  
OE:




**HEAD LAMP**  
930.TY7089E  
R:



**REAR BUMPER**  
901.TY05226BA  
OE:



**FRONT BUMPER BRACKET**  
911.TY44377  
R:



**FOG LAMP W/ COVER**  
939.TY7205Z  
OE:



**BUMPER GRILLE**  
901G.TY05053BA  
OE:





**HOOD INNER LINING**  
902A.TY1002A  
OE:



**TAIL LAMP**  
931.TY7099  
R:





**FRONT BUMPER NOZZLE HOLE COVER**  
901C.TY11004A  
OE:



**GRILLE**  
900.TY08200GA  
OE:



**HEAD LAMP STRIP CHROME**  
923.TY55162A  
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.  
Our production is not original replacement parts but interchangeable against original parts.

**TY**

email:market@daiwa-motor.com