


REPLACEMENT FOR




CADDY '97



SIDE LAMP
937.VW3585X
OE:6A0949117B






HEAD LAMP
930.VW5533 441-1127-E
R 6K5941016B L 6K5941015B



CORNER LAMP
938.VW5213 441-1517
R 6K5953050C L 6K5953049C



FOG LAMP
939.VW2007 445-2007
R 6K5941702A L 6K5941701A



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

VG

email:market@daiwa-motor.com