

REPLACEMENT FOR

RAV4 ADVENTURE '19 USA TYPE



FRONT BUMPER
901.TY05234BA
OE:52411-0R150 / 40



FRONT BUMPER GUARD
901.TY05235BA
OE:52711-0R090-B0



REAR BUMPER
901.TY05237BA
OE:52159-0R170



REAR BUMPER GUARD
901.TY05238BA
OE:52453-0R060-B1



HEAD LAMP
930.TY7085
R:81110-0R140 L:81150-0R140



BUMPER GRILLE
901G.TY05057BA
OE:53111-0R120 / 30 / 40



RADIATOR TOP COVER
911.TY44399A
OE:16681-F0020




GRILLE
900.TY08205GA
OE:53115-0R020



BUMPER GRILLE
901G.TY05058BA
OE:53112-0R170



FOG LAMP COVER
913.TY7120
R:52127-0R170 L:52128-0R170



FRONT BUMPER
901.TY05233BA
OE:52119-0R921 / 020 / 030



BUMPER GRILLE (NARROW BODY)
901G.TY05059BA
OE:53113-0R100



REAR SIDE BUMPER HYBRID
912.TY44141A
R:52161-0R907 L:52162-0R907



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com