

REPLACEMENT FOR

CAMRY '15

USA TYPE



FOG LAMP
939.TY2071
R



FRONT BUMPER
901.TY05199BA
OE:



HEAD LAMP MIDDLE EAST TYPE
930.TY7065
R:81130-06B70 L:81170-06B70



HEAD LAMP LE
930.TY7059
R



FOG LAMP LED
939.TY2072
R



BUMPER GRILLE LE
901G.TY07393GA
OE:53112-06260



FRONT DOOR
907.TY28241A
R:



HEAD LAMP BLACK LE
930.TY7060
R



BACK LAMP
933.TY7326
R



BUMPER GRILLE SE
901G.TY07394GA
OE:53112-06280



REAR DOOR
907.TY28242A
R:




HEAD LAMP SE
930.TY7061
R:



TAIL LAMP
931.TY7080
R



INNER FENDER
915.TY11231
R:53806-06140 L:53806-06170



HEAD LAMP BLACK SE
930.TY7062
R:



GRILLE
900.TY08079GA
OE



FRONT BUMPER BRACKET
911.TY44335A
RR:52535-06190 L:52536-06190



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com