

REPLACEMENT FOR

PALIO '97~




REPLACEMENT FOR

PALIO 5D 02~ SIENA 4D 02~



HEAD LAMP
930.FT5423
R 464512740 L 464512750



TAIL LAMP
931.FT5324U
R:041530111000 L:041520111000



CORNER LAMP
938.FT5125C
R 46537829 L 46537828



HEAD LAMP
930.FT1137
R:0046840519 L:0046840527



TAIL LAMP WAGON
931.FT1919 661-1919
OE:



CORNER LAMP AMBER
938.FT5125A
OE:



FOG LAMP
939.FT5041X
OE:R/L:712370401129




TAIL LAMP SOLE 07-ON
931.FT1914 661-1914-A-R
OE:



TAIL LAMP SIENA 99-4D
931.FT1922 661-1922
R 38620748 L 38630748



TAIL LAMP
931.FT5320
R:7083962 L:7083964



SIDE LAMP
937.FT5159X
OE:46804721T

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

FT

email:market@daiwa-motor.com