


REPLACEMENT FOR

# SPARK / BEAT '18



**MIRROR**  
960.CV1133E  
R:42489250 L:42489255



**FRONT BUMPER BRACKET**  
911.CV44092A  
R:94536808 L:94536815



**HEAD LAMP**  
930.CV7035E  
R:42614348 L:42614347



**GRILLE**  
900.CV97165GA  
OE:42333049 / 42333050



**REAR BUMPER BRACKET**  
911.CV44093A  
R:42621332 L:42621333



**TAIL LAMP 4D**  
931.CV7130  
R:42642368 L:42642367



**FOG LAMP**  
939.CV7050  
OE:42548992



**FRONT BUMPER**  
901.CV40247BA  
OE:42333042



**RADIATOR SUPPORT**  
904.CV30342A  
OE:J42639329



**REAR BUMPER LAMP 4D**  
932.CV7219  
R:42333894 L:42333893



**TAIL LAMP**  
931.CV7129  
R:42564718 L:42564719



**REAR BUMPER**  
901.CV40248BA  
OE:42557414 / 42557415



**INNER FENDER**  
915.CV11286  
R:42570750+42333059  
L:42570748+42333061



**REAR BUMPER 4D**  
901.CV40250BA  
OE:42333057



**REAR BUMPER LAMP**  
932.CV7218  
R:96644218 L:96644217



**BUMPER GRILLE W/CHRM MLDG**  
901G.CV04712BA  
OE:42647122



**FOG LAMP COVER**  
913.CV1048  
R:42340855 L:42340854



**REAR BUMPER BRACKET 4D**  
911.CV44094A  
R:94536818 L:94536817

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.  
Our production is not original replacement parts but interchangeable against original parts.

CV

email:market@daiwa-motor.com