

REPLACEMENT FOR

ELANTRA '19



FOG LAMP
939.HY7256
R:92302-F2500 L:92301-F2500



TAIL LAMP LED
931.HY7120
R:92402-F2600 L:92401-F2600



GRILLE W/ CHROME MID EAST TYPE
900.HY08019GA
OE:86352-F2BA0 / 86350-F2BB0



HEAD LAMP USA TYPE
930.HY7068
R:92102-F3500 L:92101-F3500



REAR BUMPER LAMP W/ LED
932.HY7033
R:92406-F2510 L:92405-F2510



TAIL LAMP USA TYPE
931.HY7121
R:92402-F3500 L:92401-F3500



GRILLE BLACK MID EAST TYPE
900.HY08020GA
OE:86350-F2AA0



HEAD LAMP
930.HY7069
R:92102-F2500 L:92101-F2500



BACK LAMP
933.HY7321
R:92404-F2500 L:92403-F2500



MIRROR ELECTRIC W/LAMP
980.HY153E
R:87620-F2580 L:87610-F2580



FRONT BUMPER USA TYPE
901.HY05031BA
OE:86511-F3500



HEAD LAMP LED
930.HY7070
R:92102-F2600 L:92101-F2600



BACK LAMP LED
933.HY7322
R:92404-F2600 L:92403-F2600



MIRROR ELECTRIC W/ LAMP HIT FLD
980.HY154E
R:



FRONT BUMPER
901.HY05035BA
OE:86511-F2AA0



FOG LAMP USA TYPE
939.HY7255
R:92302-F2510 L:92301-F2510



TAIL LAMP
931.HY7119
R:92402-F2500 L:92401-F2500



GRILLE W/ CHROME MX TYPE
900.HY08018GA
OE:86350-F3510



FRONT BUMPER LOWER USA TYPE
901.HY05033BA
OE:86591-F3500

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only. Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com

REPLACEMENT FOR

ELANTRA '19



FRONT BUMPER REINFORCEMENT
911.HY44399A
OE:64900-F2010




REAR RR. INNER FENDER
915.HY11151
R:86821-F3500 L:86822-F3500



TRAILER COVER
901C.HY0003
OE:86588-F2AA0



FRONT BUMPER LOWER
901.HY05041BA
OE:86591-F2AA0



FRONT BUMPER GRILLE SIDE
901G.HY04052BA
R:86562-F2AA0 L:86561-F2AA0




REAR FRT. INNER FENDER
915.HY11152
R:86824-F3500 L:86824-F3500



TOP COVER RADIATOR
911.HY44385A
OE:86360-F2AA0



REAR BUMPER
901.HY05036BA
OE:86611-F2AA0 / 86610-F2AB1



FRONT BUMPER MOULDING
923.HY55870A
R:86564-F2AA0 L:86563-F2AA0



HEAD LAMP BRACKET
911.HY44398A
R:92152-F2500 L:92151-F2500



RADIATOR SUPPORT
904.HY30939A
OE:64101-F3500 / F2500



REAR BUMPER LOWER
901.HY05032BA
OE:86612-F2AA0-2



FRONT INNER FENDER
915.HY11150
R:86812-F3500 L:86811-F3500



FRONT BUMPER BRACKET
911.HY44387A
R:86514-F2AA0 L:86513-F2AA0



HOOD
902.HY20962A
OE:66400-F2500




REAR BUMPER LOWER USA TYPE
901.HY05034BA
OE:86612-F3500



FRONT INNER FENDER
915.HY11156
R:86812-F2800 L:86811-F2800



REAR BUMPER BRACKET
911.HY44388A
R:86614-F2AA0 L:86613-F2AA0



FRONT FENDER
905.HY20966A
R:66320-F2500 L:66310-F2500

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com

REPLACEMENT FOR




ELANTRA '19



GRILLE
900.HY08026GA
OE:



REAR FENDER
905.HY20950A
R:71504-F2C01 L:71503-F2C01



FRONT DOOR
907.HY28110A
R:76004-F2000 L:76003-F2000



REAR DOOR
907.HY28111A
R:77004-F2000 L:77003-F2000



TRUNK LID
928.HY21034A
OE:69200-F2500



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com