

REPLACEMENT FOR

**i20 '13~**



**REAR BUMPER LAMP**  
932.HY7025  
R:



**RADIATOR SUPPORT**  
904.HY30345A  
OE: 64101-1J500



**HEAD LAMP**  
930.HY7030  
R:92102-1J510 L:92101-1J510



**MIRROR**  
980.HY123  
R:



**FRONT BUMPER REINFORCEMENT**  
911.HY44818A  
OE:86530-1J570



**FOG LAMP LED**  
939.HY7225  
R:92202-1J510 L:92201-1J510



**MIRROR ELECTRIC W/LAMP**  
980.HY124E  
R:



**REAR BUMPER REINFORCEMENT**  
911.HY44819A  
OE:86530-1J500



**FOG LAMP**  
939.HY7231  
R:92202-1J500 L:92201-1J500



**FRONT BUMPER**  
901.HY05007BA  
OE:86511-1J500



**TAIL LAMP**  
931.HY7020  
R:92402-1J500 L:92401-1J500



**REAR BUMPER**  
901.HY05008BA  
OE: 86611-1J500



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.  
Our production is not original replacement parts but interchangeable against original parts.

**HY**

email:market@daiwa-motor.com