

REPLACEMENT FOR


HILUX ROCCO '18



FRONT BUMPER
901.TY05213BA
OE:



FOG LAMP COVER (LED)
913.TY7933
R:




FOG LAMP
939.TY7197
R:



FRONT BUMPER GRILLE
901G.TY05047BA
OE:



HOOD GARNISH
923.TY55177A
OE:



GRILLE (CHROME)
900.TY08192GA
OE:





FRONT BUMPER BOARD
910.TY14252A
OE:



GRILLE (GREY)
900.TY08196GA
OE:




HOOD LOCK BRACKET
911.TY44207
R:



GRILLE (BLACK)
900.TY08197GA
OE:



FOG LAMP COVER
913.TY7934
R:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com