

REPLACEMENT FOR

L/CRUISER PRADO '14~



FRONT BUMPER
901.TY05146BA
OE:





HOOD MOULDING
923.TY55131A
OE:



HEAD LAMP
930.TY7031
OE:



REAR BUMPER
901.TY05156BA
OE:



FOG LAMP W/O BULB
939.TY7051 212-2088
R:81210-12230 L:81220-12230





BUMPER GRILLE
901G.TY05019BA
OE:



FOG LAMP CASE
913.TY7912A
OE:



FRONT BUMPER BRACKET
911.TY44307A
R:52133-60160 L:52134-60170



TAIL LAMP
931.TY191M
R:81551-60B50 L:81561-60B30



TOP COVER, RADIATOR
911.TY44308A
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com